G. R. S. 58]

Previous references. 1914-5

Memo. No. 2899-947 (800)

800 (29-24-12

File No. 49-24

Serial Nos. 10.

Later references.

PRESERVED

GENERAL AND REVENUE SECRETARIAT.

Serial Nos. one (1).

Part B for march 1925

SUBJECT

Four Roles of the first member of council in the Kaira & Broach districts for April & May 1924

From The Secretary to Govt.

P. 25 B.

No. P.S. 2523 / — 8 20-2-25

Asks a copy of statement received from the Chief Engineer of Bombay showing therein the action taken on the several items referred to in the four Roles.

Gen 3940

No. P. W. 2523. 35631

MYSORE PUBLIC WORKS DEPARTMENT,
CENTRAL OFFICE,
Dated Bangalore, 20th February 1925.

DEWAN'S OFFICE,
RECD. ON 24 FEB. 1925
Reg. No. 6205

FROM

K. R. SESHACHAR, ESQ., B.A., B.E., C.E.,
Secretary to the Government of Mysore,
Public Works and Electrical Departments,
Bangalore.

GENL. & REV. SECTION
BR. 21
21 FEB. 1925
G. D. SECTION

To

B. Ramaswamaiya, Esq., B.A., B.L.,
Chief Secretary to Government,
B a n g a l o r e.

SIR,

I have the honour to forward herewith, for information, a copy of statement received from the Chief Engineer of Mysore, showing therein the action taken on the several items referred to in the Tour Notes of the First Member of Council in the Kadur and Hassan Districts in April and May 1924, forwarded with your Memo No. G. 2897-947/G.M. 49-24-2 dated the 18th October 1924.

Submitted for perusal

I have the honour to be,

Sir,

Your most obedient servant,

K. R. Seshachar

Secretary to Government,
Public Works Department.

T.R.S.

Extract from Tour Notes of the First Member of Council in the Kadur and Hassan Districts, in April and May 1924.

No.	Subject.	Remarks.	Action so far taken.
	Kadur Division.		
1.	Local Fund Dispensary Kadur.	(a) The Dispensary building is in a state of disrepair and requires early attention. The Executive Engineer said that the work should be taken up shortly.	(a) The Dispensary building was repaired in July this year under an estimate of Rs 140.
		(b) The Dispensary building has no compound wall. Steps should be taken to construct one at an early date.	(b) Local Fund Dispensary at Kadur has got a compound wall. Perhaps this is meant for the Local Fund Dispensary at Bārur. The President District Fund Board is addressed to intimate if he will find funds for the work this year.
2.	District Hospital, Chickmagalur.	(a) The Operation Theatre is an old fashioned structure and is not suited for the purpose. For one thing, it is too close to the road with the bus traffic and other distractions and it is a real task for the Surgeon to concentrate his attention while performing operations. There are no top lights to the theatre and ventilation is also bad. The situation of the windows admits of rain water getting in and if the windows are closed, light and air will be obstructed. These defects should be rectified as early as possible.	The construction of a new Operation Theatre free from these defects will be provided for in the next year's Budget.
		(b) The soiled portion of the walls cannot in turn be washed as they are neither cemented up to a certain height or provided with glazed tiles. Steps should be taken to remedy the defect.	
3.	Attigundi	The construction of a building for the Dispensary and quarters for the sub Assistant Surgeon is a very urgent necessity.	The Ex:Engr: promises to submit early the proposals for the construction of a building in consultation with the President, District Board.

No.	Subject.	Remarks.	Action as for taken.
	Western Division Government contribution for the Gorur bridge during 1924-25.	The question is being referred to P.W.Secretariat.	Orders of Government to whom the question has been referred are awaited.

Bangalore,

February 1925.

Chief Engineer of Mysore.